

APPENDIX 17

Site Inspection Photographs



Plate 1: The Roundhouse taken from the Turntable. Photograph taken facing west



Plate 2: Representative photo of the cyclone fencing on the northern Site boundary.



Plate 3: Damaged ACM cladding on the Roundhouse with ACM fragments visible on the surface soil.



Plate 4: ACM fragments on the surface soil of one of the access tracks to the south of the Roundhouse



Plate 5: Stockpiled ACM in the Roundhouse.



Plate 6: Inside the Roundhouse facing north. Several of the 14 bays are visible. Wiring can be seen at the base of the service pit.



Plate 7: Waste (tyres, plastic, concrete, steel) observed in one of the service pits in the Roundhouse.



Plate 8: Minor staining on the timber floors within the Roundhouse.



Plate 9: The workmen’s carriage in the Roundhouse, located in the northern bay.



Plate 10: The two half drums on the triple interceptor trap. The drum on the right of the image contains the tar-like product, the other on the left was empty.



Plate 11: The Turntable, photo facing south.



Plate 12: The Turntable, photo facing north.



Plate 13: The operators shed on the Turntable.



Plate 14: Inside the operators shed on the Turntable.



Plate 15: Turntable platform, looking north-west towards the manual operation pulley. The rusted steel and degraded decking are visible.



Plate 16: Distressed vegetation observed beneath the Turntable.



Plate 17: Photo of low-lying vegetation on the eastern portion Lot 561.



Plate 18: Dark grey sand encountered during the Site inspection.



Plate 19: White sand encountered during the Site inspection.



Plate 20: The ironstone laterite observed on the access tracks in Lot 561. Photo facing to the south towards the Site entrance.



Plate 21: ACM observed in the fill material in Lot 561.



Plate 22: Black ash material observed on the Site surface near the northern boundary.



Plate 23: Steel rails that were observed on the soil surface of Lot 561.



Plate 24: A second location where steel rails that were observed on the soil surface of Lot 561.



Plate 25: The undulating nature of Lot 561. Image facing to the east.



Plate 26: Stockpile SP1.



Plate 27: Stockpile SP2.



Plate 28: Stockpile SP3.



Plate 29: Stockpile SP4.



Plate 30: Stockpile SP6.



Plate 31: Stockpile SP7.



Plate 32: Stockpile SP8.



Plate 33: The concrete observed at the location of former groundwater well MB2.



Plate 34: One of the soak wells observed in the eastern portion of Lot 561. The well was observed to sit atop the soil surface .



Plate 35: The second unused soak well observed on Lot 561. Fragments of concrete are visible within the soak well.



Plate 36: Example of the topography and vegetation on Lot 2860, photo taken facing towards the south-west.



Plate 37: The two buildings (Compressor Shed on the left and unknown building on the right) located on Lot 560, west of the Roundhouse.



Plate 38: The Compressor Shed. Photo facing south. The compressed air reservoir can be observed to west (right) of the compressor shed.



Plate 39: The damaged ACM cladding on the Compressor Shed. ACM fragments can be observed on the soil surface around the Shed.



Plate 40: Inside the Compressor Shed. ACM fragments and black discolouration on the walls and concrete floor can be observed.



Plate 41: The unknown building present on Lot 560, west of the Compressor Shed.



Plate 42: Dark soil observed north of the Compressor Shed on Lot 560.



Plate 43: Stored railway waste on Lot 2856. The burned railway sleepers can be observed in the foreground



Plate 44: Stockpile SP9.



Plate 45: Sand AST to the left, nitrate/chromate AST in the centre and shed to the right. Photo taken looking north, approximately 75 north of the Roundhouse.



Plate 46: Offsite Aurizon Diesel AST, photo taken looking towards the north-west.



Plate 47: Underground drainage release point at ephemeral creek, located offsite.



Plate 48: Sewage disposal location, near Collie Information Centre, south of Lot 2860.



Plate 49: The location of the former Nightowl service station, east of the Site.



Plate 50: Northern wall embankment with C&D waste observed, offsite.



Plate 51: Aurizon Collie Depot Trade Waste Treatment Plant sign on brick building, west of the Site.



Plate 52: The three concrete lids, understood to be the septic tanks associated with the Aurizon Administration building.